

# IPSWD/IPSWD-RWB Installation Template for surface mount applications

- Place template on mounting surface, aligning keyed mounting holes on right side of enclosure with structural features (stud)
- Ensure access port "A" is aligned with wiring source (junction box)
- Mark location that fasteners will attach to using the centerline marks provided
- Remove template from mounting surface
- Place enclosure on mounting surface and mark location that fasteners will attach to on left side of enclosure
- Feed CAT5 cable through access port "A" in enclosure
- Fasten enclosure at previously marked locations

